mObridge – APPLICATION REFERENCE for Audi MMI-MOST software versions

APPLIES TO: mObridge Bluetooth ABT2010-AUD-F for Audi MMI-MOST



APPLICATIONS:

Model	Model Years	Compatible Radios	Limitations
A6	05 -09		
A8	04 -08		
Q7	07-09	Audi MMI on MOST	
RS6	08-09	Addi Wilvii OH WOST	
S6	07-09		
S8/R8	08-09		
Allroad	08-09		Model not available in U.S.



Setup

SW: D3-HU 55.7.0 0839



Background:

Audi MMI on MOST, particularly in 2004-2006 models, had "buggy" Bluetooth/telephone software. Installer should always check the Audi MMI software version in the car prior to sales/installation to determine if a software update to the Audi MMI system will be required.

Procedure:

Determine the Audi MMI main software version. Under car settings (setup) menus, you should find the main MMI version. Try button 'Car' then under Setup > Version. On the top line should read something like:

Example versions: SW: D3-HU 6300 07.7.0 0406 (means version 0770 – needs updating) SW: D3-HU 33.6.0 0632 (means version 3360 – new enough, OK) (12-digit format) (8-digit format) SW: D3-HU XXXX YY.Y.ZZZZ or YY.Y.Y ZZZZ (see photo to the right, example has MMI software version 5570, which is new enough to support BT/telephone) main Audi MMI software version – this example it's version 5570 which is new enough to properly support telephone/BT.

The YY.Y.Y is what you are looking for, this is the main MMI software 'index' or version:

- If it's between 0500 and 2860 the MMI software is **too old** to properly support BT/telephone and **needs to be updated**. Dealer can do this or it can be done with Audi parts CDs/DVDs.
- If it's somewhere at least 3600 or 4200, the MMI is probably sufficiently up-to-date (at least new enough not to be so buggy with BT/telephone).

After the Audi MMI has been ensured to be properly up-to-date, you can proceed* with installation.

(*NOTE: one other 'gotcha' with Audi MMI installations: make sure there is not an existing MOST BT/telephone unit. Typically in Audis this is under the driver's seat, protected in a plastic box with other ECU's. The Audi MMI system, like any other MOST system, is not designed to accommodate more than one telephone unit. A conflicting telephone unit must by bypassed using a MOST bypass loop or inline connector on the fibers.)