



## Latest Firmware for the mObridge DA1 Preamp

|   |                 |
|---|-----------------|
| <b>Version</b>  | 1.9.2           |
| <b>Released On</b>  | 22nd March 2019 |
| <b>Fixes</b>  |                 |
| <ul style="list-style-type: none"> <li>• Soft bypass added controllable from the GUI</li> <li>• Landrover and Jaguar volume control bugs fixed that was causing no audio</li> <li>• Non-volatile memory write debounce added</li> </ul> |                 |

|   |                             |
|---|-----------------------------|
| <b>Version</b>  | 1.9.0                       |
| <b>Released On</b>  | 3 <sup>rd</sup> August 2018 |
| <b>Fixes</b>  |                             |
| <ul style="list-style-type: none"> <li>• BMW NBT and NBT Evo radios added to the compatibility</li> <li>• BMW volume control architecture changed to improve responsiveness</li> <li>• Landrover and Jaguar volume control architecture changed to improves responsiveness</li> </ul> |                             |

## Latest Firmware for the mObridge DA1 Preamp

|  |                             |
|--|-----------------------------|
| <b>Version</b>   | 1.8.0                       |
| <b>Released On</b>   | 16 <sup>th</sup> April 2016 |
| <b>Fixes</b>   |                             |
| <ul style="list-style-type: none"> <li>• Landrover Gen 2 updates to fix mono PDC audio issue</li> <li>• Landrover Gen 2 updates to add error message handling on MOST</li> <li>• BMW re-mapped volume curve for the first 6 notches</li> <li>• Volvo Gen 2 updates to fix mono source mapping to volume control</li> <li>• Jaguar compatibility added</li> <li>• Mono source buffering decreased for better echo on phone and PDC delays</li> <li>• Porsche PCM3 balance and fade fix</li> <li>• Volvo ignition control bug fixed</li> <li>• Multiple bug fixes</li> </ul> |                             |

|  |                               |
|--|-------------------------------|
| <b>Version</b>   | 1.7.5                         |
| <b>Released On</b>   | 26 <sup>th</sup> October 2015 |
| <b>Fixes</b>   |                               |
| <ul style="list-style-type: none"> <li>• Extra long MOST messages causing exception fixed</li> </ul> |                               |

|  |                            |
|--|----------------------------|
| <b>Version</b>   | 1.7.0                      |
| <b>Released On</b>   | 22 <sup>nd</sup> July 2015 |
| <b>Fixes</b>   |                            |
| <ul style="list-style-type: none"> <li>• Mercedes NTG2.5 &amp; NTG4.x systems volume command fixed</li> <li>• BMW chimes and PDC beeps volume turned down</li> <li>• Volvo NAV systems volume command variation fixed</li> </ul> |                            |

## Updating Your Firmware

Your mObridge DA1 product is fully firmware updatable and can be updated in the following ways. Refer to our website at [www.mobridge.us](http://www.mobridge.us) for further information.

### Via the mObridge Update Wizard

Download and install the mObridge Update Wizard from <http://www.mobridge.us/wizard>.

## Past Firmware Versions

|                    |  |
|--------------------|--|
| <b>Version</b>     |  |
| <b>Released On</b> |  |
| <b>Fixes</b>       |  |
|                    |  |