MOBRIDGE ▸ M2.CONNECT ▸ DIP SWITCH SETTINGS

DIP Switch settings for the M2.Connect for CAN can be found in the tables below.
This document is not a complete compatibility chart. For up-to-date vehicle compatibility please consult our website.

Use a small screwdriver to change the DIP switches on the M2.Connect. The unit will automatically reset with the new settings. In some vehicles it may be necessary to remove the key and allow the vehicle to sleep (lock doors and wait 10 minutes), to ensure that the head-unit restarts and recognizes the new device.

VW



Radio
Any

Audi



Radio
Any

MOBRIDGE ▸ M2.CONNECT ▸ DIP SWITCH SETTINGS

DIP Switch settings for the M2.Connect for CAN can be found in the tables below.
This document is not a complete compatibility chart. For up-to-date vehicle compatibility please consult our website.

Use a small screwdriver to change the DIP switches on the M2.Connect. The unit will automatically reset with the new settings. In some vehicles it may be necessary to remove the key and allow the vehicle to sleep (lock doors and wait 10 minutes), to ensure that the head-unit restarts and recognizes the new device.

VW



Radio
Any

Audi



Radio
Any

mobridge BRIDGING MEDIA, COMMUNICATION & LIFESTYLE WITH YOUR VEHICLE | WWW.MOBRIDGE.US PAGE | 1

MOBRIDGE ▸ M2.CONNECT ▸ DIP SWITCH SETTINGS

DIP Switch settings for the M2.Connect for CAN can be found in the tables below.
This document is not a complete compatibility chart. For up-to-date vehicle compatibility please consult our website.

Use a small screwdriver to change the DIP switches on the M2.Connect. The unit will automatically reset with the new settings. In some vehicles it may be necessary to remove the key and allow the vehicle to sleep (lock doors and wait 10 minutes), to ensure that the head-unit restarts and recognizes the new device.

VW



Radio
Any

Audi



Radio
Any

MOBRIDGE ▸ M2.CONNECT ▸ DIP SWITCH SETTINGS

DIP Switch settings for the M2.Connect for CAN can be found in the tables below.
This document is not a complete compatibility chart. For up-to-date vehicle compatibility please consult our website.

Use a small screwdriver to change the DIP switches on the M2.Connect. The unit will automatically reset with the new settings. In some vehicles it may be necessary to remove the key and allow the vehicle to sleep (lock doors and wait 10 minutes), to ensure that the head-unit restarts and recognizes the new device.

VW



Radio
Any

Audi



Radio
Any

mobridge BRIDGING MEDIA, COMMUNICATION & LIFESTYLE WITH YOUR VEHICLE | WWW.MOBRIDGE.US PAGE | 1