Latest Firmware for mObridge M2.Connect

Version	1.12.9
Released On	20/6/2016
Fixes	

- Fixing iPhone pairing issue, and auto-connect. **[ALL VEHICLES]**
- Fixing some MOST instability in rare cases **[ALL VEHICLES]**

Updating Your Firmware

Your mObridge M2 product is fully firmware updatable and can be updated in the following ways. Refer to our website at www.mobridge.us for further information.

Via USB Drive

This is the easiest way to upgrade your M2 firmware. Simply copy the firmware file to a USB thumb drive and insert in to the USB port on the M2. The M2 will automatically update to the new firmware and restart.

Via the mObridge Update Wizard

(This method requires a special USB cable to work correctly)
Download and install the mObridge Update Wizard from http://www.mobridge.us/wizard.

Via mObridge Android App (Bluetooth equipped products only)

Download the mObridge Android App via the Google Play Store.

Previous Releases

Version	1.12.8
Released On	7/6/2016
Fixes	

- Improve reliability of A2DP connections. **[ALL VEHICLES]**
- Fixing high-frequency tone during A2DP streaming **[ALL VEHICLES]**

Version	1.12.2
Released On	26/9/2015
Fixes	

- Switch to Bluetooth Simple Secure Pairing. No PIN Code is now required when pairing to the system. This fixes a lot of issues with Android phones, where the PIN code entry would time out. **[ALL**

VEHICLES]
- Fixing issue where phonebooks sometimes don't show up **[PORSCHE]**