



mObridge → DA-G2 MOST25 → Firmware Release Notes

Latest Firmware for mObridge DA-G2 MOST25 products:

Version	2.6.10
Release Date	6 th June 2022
Fixes	<ul style="list-style-type: none">• Fixing broken sub control in Audi MMI3G• Some performance enhancements

Updating Your Firmware

Your mObridge DA-G2 product is fully firmware updatable and can be updated in the following ways:

Via mObridge DSP:

Download and install mObridge DSP from mobridge.us/mobridge-dsp-pc-application

Via mObridge Updater:

Download and install mObridge Updater from mobridge.us/firmware-update/

Refer to our website at mobridge.us for further information.

Past Firmware Versions

Version	2.6.9
Release Date	5 th May 2022
Fixes	
<ul style="list-style-type: none"> • Frequency response correction implemented. • Fixing Left/Right input mismatch. 	

Version	2.6.7
Release Date	8 th July 2021
Fixes	
<ul style="list-style-type: none"> • Fixing MDI null app name issue. 	

Version	2.6.6
Release Date	6 th July 2021
Fixes	
<ul style="list-style-type: none"> • Fixed stack overflow issue regarding DSP core. 	

Version	2.6.4
Release Date	17 th June 2021
Fixes	
<ul style="list-style-type: none"> • Adding explicit Toyota Supra vehicle support for mObridge DSP and mObridge Updater • Fixing various BMW issues related to multichannel audio, ignition, and turn on/off time. • Fixing issue with corrupted NVM regarding improper boundary checks on input delay field. 	

Version	2.6.0
Release Date	20 th May 2021
Fixes	
<ul style="list-style-type: none"> • Changing Land Rover, Aston Martin, Jaguar, and Volvo DIP switch settings to be compatible with new revision 3 of the DA-G2 baseboard. Please refer to the latest DIP switch settings document. 	

Version	2.5.5
Release Date	14 th May 2021
Fixes	
<ul style="list-style-type: none"> • Fixing BMW loopback echo issue. • Fixing broken fade/balance controls in Aston Martin. • Fixing Porsche PCM3.x phone echo issue. • Fixing improper reset of input delay in NV. 	

Version	2.5.2
Release Date	1 st March 2021
Fixes	
<ul style="list-style-type: none"> • Fixing Audi MMI3G head-unit preset selection control. • Fixing Audi MMI3G head-unit subwoofer gain control. 	

Version	2.5.1
Release Date	18 th February 2021
Fixes	
<ul style="list-style-type: none"> • Fixing logical input gain index mismatch with mObridge DSP. • Revamped logging type names. • Added support for AT25SF321B SPI flash chip. 	

- Slight performance fixes for Audi MMI3G vehicle compatibility layer.

Version	2.4.0
Release Date	20 th November 2020
Fixes	
<ul style="list-style-type: none"> • Sub-woofers/Woofers now use IIR filtering only for the channel EQ to improve low range frequency response, and its precision when tuning. • Vastly improved THD on Sub-woofer/Woofer channels. • Various performance optimizations to the DSP core. 	

Version	2.2.0
Release Date	16 th September 2020
Fixes	
<ul style="list-style-type: none"> • Addition of Aston Martin vehicle variants. • Increasing gain resolution to 0.1 dB increments. • Middle LED now indicates present of MOST25 network. • Sub-woofers now use IIR filters over FFT filters to improve low-frequency response. • DA-G2.Standard product now has TOSLINK channels mapped by default. • Various performance optimizations to the DSP core. 	

Version	2.1.0
Release Date	18 th June 2020
Fixes	
<ul style="list-style-type: none"> • Fixing broken factory head-unit bass/mid/treble integration with the DSP. • Fixing crash associated with NV memory. 	

Version	2.0.0
Release Date	24 th April 2020
Fixes	
<ul style="list-style-type: none"> • Adding secondary minimal recovery application. • Reduction in code size. • Fixes for elusive phone echo issues. • MOST25 network fixes for Mercedes-Benz vehicles. • Channel count issue with Standard variant resolved. • Boot performance vastly improved. <p>IMPORTANT NOTE: <i>This firmware will become a MINIMUM version for all future firmware updates. This firmware MUST be flashed prior to upgrading to any newer firmware. Doing otherwise severely risks bricking the unit.</i></p>	

Version	1.2.0
Release Date	31 st March 2019
Fixes	
<ul style="list-style-type: none"> • Fixing a variety of issues regarding mono channels, including throughput, noise, filtering. • Improved delay on mono channels, and added a mono channel delay adjuster for fine-tuning perceived echoes. (e.g. phone audio). • Miscellaneous MOST25 fixes. • Addition of center-channel upmixing algorithms. 	

Version	1.1.0
Release Date	29 th January 2019
Fixes	
<ul style="list-style-type: none"> • #416 Fix broken connect/disconnect timeout function on MOST25 	

Version	1.1.0
Release Date	15 th December 2019
Fixes	
<ul style="list-style-type: none">• Audio quality improvements for stereo channels, with certain crossover frequencies.• Improve audio quality of mono channels• Fix missing PDC audio (BMW)	

Version	1.0.1
Release Date	18 th September 2019
Fixes	
<ul style="list-style-type: none">• Initial Release!• Fix Analog Output Mappings• Updated for 12 Channels of DSP Processing• Updated for TOSLINK Support• Fixes Factory Reset communication with mObridge DSP• Fix Storing of DSP Parameters to NVM	