



mObridge Updater Application Release Notes

[22.07.00] - 2022-07-13

Added

- Support for MOST150 oPHY/cPHY and A2B Ford K2 DSP/amplifiers.

[22.06.00] - 2022-06-23

Added

- Support for 16-bit filter bins.

[22.05.00] - 2022-05-09

Changed

- Fixes for macOS Monterrey.

[22.03.02] - 2022-03-17

Added

- Support for scaling on high DPI screens.

Changed

- Fixed LW console debug log copy, save, and backspace issues.
- New debug console font.
- Fixing issue with licence file packaging.



mObridge Updater Application Release Notes

[22.03.01] - 2022-03-11

Changed

- Addition of LW debug enable message

[22.03.00] - 2022-03-07

Changed

- Fixing connect issue with misc. products.

[22.02.03] - 2022-02-25

Added

- Adding ability to change devices, debug console for developers.
- Adding recovery panel for devices in recovery mode.

Changed

- Fixing missing Options and Tools menu in 21.11.00

[21.11.00] - 2021-11-05

Changed

- Fixing automatic updater module incorrectly choosing manual update.



mObridge Updater Application Release Notes

[21.10.00] - 2021-10-28

Changed

- Adding product support for M1 amp, and latest DSP app version.

[21.09.00] - 2021-09-10

Changed

- Fixing broken product connectivity with legacy products.

[21.08.00] - 2021-08-18

Changed

- Fixing broken auto firmware updater URL, as webserver is now redirecting links.

[21.07.02] - 2021-07-08

Changed

- Fixing zero-length string for DSP settings 'name' field.

[21.07.01] - 2021-07-05

Changed

- Minor bugfixes, routine release.



mObridge Updater Application Release Notes

[21.06.00] - 2021-06-10

Changed

- Fixes for broken vehicle selector.

[21.05.02] - 2021-05-21

Changed

- Fixes for macOS on Big Sur
- Fixes for M2 series Bluetooth configuration options.

[21.05.01] - 2021-05-14

Added

- Fixing DA-G2 A2B Standard feature compatibilities.
- Fixing broken UI loading spinner.

[21.05.00] - 2021-05-06

Added

- Support for OBD Coding Tool (BMW) products.

[21.04.00] - 2021-04-26

Added

- Support for DA-G2 MOST150 COAX product range.



mObridge Updater Application Release Notes

[21.03.01] - 2021-03-26

Added

- Re-adding Porsche PCM3.x vehicle option.

[21.03.00] - 2021-03-18

Added

- Support for LW updater protocol.
- Support for ATSAM products.

Changed

- User interface tweaks and improvements.

[21.02.01] - 2021-02-19

Changed

- Support for logical inputs versus input channels.

[21.02.00] - 2021-02-09

Changed

- Fixed main window sizing issues for certain products.
- Fixed Bluetooth form issues for M2 series of products.
- Fixed the MOST bypass switch UI functionality.



mObridge Updater Application Release Notes

[21.01.00] - 2021-01-29

Changed

- Minor bugfixes
- Updated product descriptions and images

[20.11.00] - 2020-11-18

Added

- Biquad IIR cascaded filtering support

[20.10.01] - 2020-10-14

Changed

- Fixed misnamed Windows shortcuts and Start menu entries.

[20.10.00] - 2020-10-06

Added

- Initial macOS release.

Changed

- Fixed missing logo on version information dialog.
- Fixed misnamed Windows shortcuts and Start menu entries.



mObridge Updater Application Release Notes

[20.09.02] - 2020-09-30

Changed

- Addition of 16-bit gains for DSP-enabled products.

[20.09.01] - 2020-09-15

Changed

- Fixing issue with vehicle selection.

[20.09.00] - 2020-09-09

Changed

- Support for Bluetooth version on M2 products

[20.08.01] - 2020-08-26

Added

- Support for mObridge DAB products

Changed

- Various user interface improvements

[20.08.00] - 2020-08-19

Added

- Initial release

